



PTO SWITCH	
POSITION: ON	CIRCUIT MAKE
POLE 1: C & B	POLE 2: F & E
POLE 3: H & G	
POSITION: OFF	CIRCUIT MAKE
POLE 1: C & A	POLE 2: F & D
POLE 3: OPEN	

IGNITION SWITCH	
POSITION	CIRCUIT MAKE
1. OFF	G & M & A
2. RUN	B & L & A
3. START	B & L & S

5415669 / JUMPER HARNESS

